




QUICK GUIDE

AP-1 COMPACT ACOUSTIC PREAMP/D.I.



1. This is where you connect the cable from your acoustic guitar.
2. Main output to FOH/Mixing desk.
Transformer balanced 3-pin XLR male bushing.
Pin 2 is hot, pin 3 is cold, and pin 1 is ground/screen.
3. Isolated Tuner Output. Always active.
4. 9-18VDC @ 100mA. Center negative. Will accept both 2.1 and 2.5mm plug.